

**Subject:** Revision of the maintenance manual

**Applicability:** **AS 33 Es**; Type-Certificate EASA.A.656

**Urgency:** mandatory, 31.12.2023

**Reason:** Improvement of documentation

**Action:** The following pages of the manuals have to be exchanged:

Maintenance Manual German: 2.36, 2.39, 2.60, 5.1, 12.3, 12.7, 13.4

Maintenance Manual English: 2.36, 2.39, 2.60, 2.67, 3.2, 5.1, 9.6, 12.3, 12.7, 13.4

The new manual pages are marked with the technical note number TN 8 from 11.04.2023 as revision.

The exchange of the pages has to be noted in the record of revision of the manual. The list of effective pages must be updated, too.

**Material and Drawings:** see action

**Mass and Balance:** No change on the mass and C. of G. position.

**Notes:** The revision of the maintenance manual has to be considered as a pilot-owner maintenance task regarding aviation law. The respective regulations must be applied.

Poppenhausen, 07.08.2023

**Alexander Schleicher**  
GmbH & Co.

i.A.   
(T. Mörsel)

This Technical Note bases on a change, which was approved by EASA under the minor change approval EASA 10082506.