

Doc.-Nr.	300.99.0001	Technical Note	Alexander Schleicher GmbH & Co. Segelflugzeugbau
Issue: 00		ASH 30 Mi – TN 9	D-36163 Poppenhausen
Page: 1 of 1		Fuel main filter	ADOA AP138
<div>Issue date:09.10.2023</div> <div>Subject:Introduction of an alternative fuel main filter due to end of production of the existing one.</div> <div>Applicability:ASH 30 Mi, all serial numbers</div> <div>Urgency:optional</div> <div>Material:50.000.0224 Fuel filter</div> <div>Drawings:See Action</div> <div>Mass and Balance:The change in mass and C. of G. position is negligible.</div> <div>Notes:<div>The replacement of the fuel filter has to be considered as a non-complex maintenance task regarding aviation law. The respective regulations must be applied.</div><div>The exchange of the manual pages has to be considered as a pilot-owner maintenance task regarding aviation law. The respective regulations must be applied.</div></div> <div>Approval:This Technical Note bases on a change, which was approved by EASA under the minor change approval EASA 10083152.</div> <div>Actions<div>If, for instance during maintenance, the fuel main filter has to be replaced, an alternative filter with AS P/N 50.000.0224 can be obtained from Alexander Schleicher and installed instead of the existing one.</div><div>The following manual pages have to be exchanged against new pages with the revision "TN 9 09.10.2023":<div>Maintenance Manual: 7.10</div></div><div>The exchange of the pages has to be noted in the record of revision of the manual. The list of effective pages must be updated, too.</div></div>			