

Doc.-No. <b>340-99-0001-00</b> Issue: 05 Date: 05.07.2024 Page: 1 of 11	<b>List of applicable publications</b>	 <b>Alexander Schleicher GmbH &amp; Co.</b> <b>Segelflugzeugbau</b>  Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	<b>AS 34 Me</b>	

**Section A: Manuals**

Doc.-Number	Name	Issue	Date	Model	Serial-Numbers	Applicability										Remarks	
						EASA	Australia										
<b>Aircraft flight manuals</b>																	
---	Flughandbuch für den eigenstartfähigen Motorsegler AS 34 Me (German)	---	01.09.2021	AS 34 Me	all	X	-										
---	Flight manual for the powered sailplane AS 34 Me (English)	---	01.09.2021	AS 34 Me	all	X	X										
<b>Supplements to aircraft flight manual</b>																	
---	Ergänzung A – Laden der Hochvolt-Batterien im Anhänger (German)	---	01.09.2021	AS 34 Me	all	X	-										
---	Supplement A – Charging the high-voltage batteries inside the trailer (English)	---	01.09.2021	AS 34 Me	all	X	X										
340-99-0006-00	Supplement B – Steerable tail-wheel	---	01.10.2024	AS 34 Me	all	X	X										For aircrafts with service bulletin TN 6 only
340-99-0006-01	Ergänzung B – Lenkbares Spornrad	---	01.10.2024	AS 34 Me	all	X	X										For aircrafts with service bulletin TN 6 only









Doc.-No. <b>340-99-0001-00</b> Issue: 05 Date: 05.07.2024 Page: 6 of 11	<b>List of applicable publications</b>	 <b>Alexander Schleicher GmbH &amp; Co.</b> <b>Segelflugzeugbau</b>  Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	<b>AS 34 Me</b>	

General maintenance instructions														
---	Wartungsanweisung „Alle GFK-Muster“ <a href="#">(German)</a>	02	02.11.2020	AS 34 Me	all	X	-							
	Maintenance instruction „All FRP glider models“ <a href="#">(English)</a>					X	X							
---	Wartungsanweisung über den Einbau von Ausrüstung <a href="#">(German)</a>	02	25.04.2016	AS 34 Me	all	X	-							
	Maintenance instruction installation of equipment <a href="#">(English)</a>					X	X							
---	Wartungsanweisung „LACK-RISSE“ <a href="#">(German)</a>	---	26.06.1989	AS 34 Me	all	X	-							
	Maintenance instruction “PAINT CRACKS” <a href="#">(English)</a>					X	X							

Doc.-No. <b>340-99-0001-00</b> Issue: 05 Date: 05.07.2024 Page: 7 of 11	<b>List of applicable publications</b>	 <b>Alexander Schleicher GmbH &amp; Co.</b> <b>Segelflugzeugbau</b>  Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	<b>AS 34 Me</b>	

### Section C: Service bulletins

Doc.-Number	Name	Issue	Date	Applicability												categorisation <sup>1</sup>	manual rev. <sup>2</sup>	urgency	Remarks
				Model	Serial No.	EASA	Australia												
<b>Type-specific service bulletins</b>																			
AS 34 Me TN No. 1	Alternative Batteriezellen für Antriebsbatterie <a href="#">(German)</a>	---	01.10.2022	AS 34 Me	all	X	-										O	AFM AMM	---
	Alternative battery cells for the propulsion battery <a href="#">(English)</a>					X	X												
AS 34 Me TN No. 2	Schwerpunktkupplung <a href="#">(German)</a>	---	22.03.2023	AS 34 Me	all	X	-										O	AMM Sup	none
	C.G.-hook <a href="#">(English)</a>					X	X												
AS 34 Me TN No. 3	Ergänzung Wartungshandbuch <a href="#">(German)</a>	---	07.08.2023	AS 34 Me	all	X	-										M	AMM	31.12.2023
	Revision of the maintenance manual <a href="#">(English)</a>					X	X												
340.99.0004	AS 34 Me - TM 4 Gültige Software-Versionen <a href="#">(German)</a>	00	01.11.2023	AS 34 Me	all	X	-										M	---	none
	AS 34 Me - TN 4 Approved software versions <a href="#">(English)</a>					X	X												

<sup>1</sup> M = Mandatory, R = Recommended, O = Optional

<sup>2</sup> AFM = Revision of Flight Manual, AMM = Revision of Maintenance Manual, -Sup = New supplement to AFM / AMM

Doc.-No.  
**340-99-0001-00**  
 Issue: 05  
 Date: 05.07.2024  
 Page: 8 of 11

**List of applicable publications**

---

**AS 34 Me**



**Alexander Schleicher GmbH & Co.**  
**Segelflugzeugbau**

Alexander-Schleicher-Straße 1  
 D-36163 Poppenhausen  
 (Wasserkuppe)

Doc.- Number	Name	Issue	Date	Applicability												categorisation <sup>1</sup>	manual rev. <sup>2</sup>	urgency	Remarks
				Model	Serial No.	EASA	Australia												
340-99-0005-00	AS 34 Me – TM 5 Sicherung des Triebwerks- instruments ( <a href="#">German</a> )	00	21.05.2024	AS 34 Me	all	X	-								M	AMM	at the next scheduled maintenance action		
	AS 34 Me – TN 5 Fuse of the power-plant in- strument ( <a href="#">English</a> )					X	X												
340-99-0008-01	AS 34 Me – TM 6 Einbau eines lenkbaren Spornrads ( <a href="#">German</a> )	00	01.10.2024	AS 34 Me	all	X	X								O	AFM sup AMM sup	none		
340-99-0008-00	AS 34 Me – TN 6 Installation of a steerable tailwheel ( <a href="#">English</a> )	00	01.10.2024	AS 34 Me	all	X	X								O	AFM sup AMM sup	none		





Doc.-No. <b>340-99-0001-00</b> Issue: 05 Date: 05.07.2024 Page: 10 of 11	<b>List of applicable publications</b>	 <b>Alexander Schleicher GmbH &amp; Co. Segelflugzeugbau</b>  Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	<b>AS 34 Me</b>	

TN No. 02-2020	Einbau AIR Control Display 57 (ACD-57) als primärer Höhenmesser <a href="#">(German)</a>	02	21.02.2023	AS 34 Me	all	X	-											O	---	none	
	Installation of AIR Control Display 57 (ACD-57) as primary altimeter <a href="#">(English)</a>					X	X														

## Section D: Service information

Doc.-Number	Name	Issue	Date	Applicability														categorisation <sup>3</sup>	manual rev. <sup>4</sup>	urgency	Remarks
				Model	Serial No.	EASA	Australia														
99.090.9028	Arbeitsanweisung "Einbau Flarmantenne hinter FW-Klappe" (German)	D	05.01.2023	AS 34 Me	all	X	X											O	--	none	

<sup>3</sup> M = Mandatory, R = Recommended, O = Optional

<sup>4</sup> AFM = Revision of Flight Manual, AMM = Revision of Maintenance Manual, -Sup = New supplement to AFM / AMM

Doc.-No. <b>340-99-0001-00</b> Issue: 05 Date: 05.07.2024 Page: 11 of 11	<b>List of applicable publications</b>	 <b>Alexander Schleicher GmbH &amp; Co.</b> <b>Segelflugzeugbau</b>  Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	<b>AS 34 Me</b>	

## Section E: Notes

1. For countries not listed in the tables the owner/operator of the aircraft has to check the applicability of the respective Manual/Service-Bulletin/Service-Info based on the national legal regulations.
2. Mandatory and recommended Service-Bulletins or Service-Information has to be followed by the owner/operator of the aircraft. Non-compliance leads to exclusion of any liability.
3. The applicability of Revisions or Supplements to approved manuals (Flight / Maintenance / Repair) depends on the configuration of the aircraft and has to be checked for each individual serial number.

## Section F: Change Record

Issue	Date	Changes
00	24.08.2023	Initial issue
01	29.08.2023	Structure updated
02	29.08.2023	Links added
03	02.11.2023	Service bulletin 340.99.0004, maintenance instructions 340.99.0002 and 340.99.0003 added
04	05.07.2024	Service bulletin 340-99-0005-00 and section F "Change Record" added
05	07.10.2024	Service bulletin 340-99-0008-00 and 340-99-0008-01 as well as manual supplements 340-99-0006-00, 340-99-0006-01, 340-99-0007-00 and 340-99-0007-01 added