

Table of AD-Notes and Technical Notes

ALEXANDER SCHLEICHER

GMBH & CO

Segelflugzeugbau
D-36163 PoppenhausenType: **ASK 21Mi**Data Sheet No.: **EASA.A.221**Sheet: **1 of 4**License: **DE.21G.0010**

TN-No	AD-No. Issue Date	TN Issue Date	Version & Serial no.s affected	Subject	Compliance	Inspection Ref.
1		08.01.08 part of type-certificate	all ASK 21 Mi	Additional, removable trim ballast in the fuselage nose	Optional	
2		01.03.09 EASA-app.: 08.04.09	all ASK 21 Mi	(A) Rudder actuated by means of a hand lever at the left cockpit wall in the front pilot seat (B) Rudder actuated by means of a hand lever at the left cockpit wall in the rear pilot seat (C) Parting point between pedals and rudder control system (D) Additional wheel brake lever on the front control stick	Optional	
3		01.07.09 EASA-app.: 09.07.09	all ASK 21 Mi	Lithium iron phosphate batteries used as engine batteries	Optional	
4		09.09.09 EASA-app.: 19.10.09	all ASK 21 Mi	Modification of the fuel-supply line	Optional	
5		01.06.10 EASA-app.: 18.08.10	all ASK 21 Mi	Alternative rim for main wheel	Optional	
6		01.06.10 EASA-app.: 18.08.10	all ASK 21 Mi	Wheel brake lever on the control stick	Optional	

Table of AD-Notes and Technical Notes

ALEXANDER SCHLEICHER

GMBH & CO

Segelflugzeugbau
D-36163 Poppenhausen

Type: **ASK 21Mi**

Data Sheet No.: **EASA.A.221**

Sheet: **2 of 4**

License: **DE.21G.0010**

TN-No	AD-No. Issue Date	TN Issue Date	Version & Serial no.s affected	Subject	Compliance	Inspection Ref.
7	EASA AD 2013-0123 05.06.13 LBA LTA 2013-161 10.06.13	12.12.12 EASA-app.: 12.03.13	all ASK 21 Mi	Trim ballast for spin flights (spin ballast)	Before the next flight with spin ballast, but not later than 31. May 2013	
8		01.03.12 EASA-app.: 30.05.12	all ASK 21 Mi	Modification of the lever, which prevents the front canopy to be locked, while the rear canopy is unlocked	Optional	
9		19.09.14 EASA-app.: 19.09.14	all ASK 21 Mi	Trouble shooting of the Engine Control Unit (ECU)	see Austro Engine Mandatory Service Bulletin No. MSB-AE50R-006	
10		01.04.15 EASA-app.: 07.05.15	all ASK 21 Mi	(A) New calibration of the rotor internal cooling temperature depending on the position of the temperature sensor (B) Various corrections of the manuals	Optional	
11 Issue II	EASA AD 2017-0136 31.07.17	19.07.17 EASA-app.: 18.05.16	all ASK 21 Mi	Replacement of the silencer	Replacement of the existing silencer after 150 engine hours, at the latest	
12		29.03.16 EASA-app.: 19.05.16	all ASK 21 Mi	Wheel Brake Lever on the Stick	Optional	
13		01.08.17 EASA-app.: 19.05.16	all ASK 21 Mi	Modified brake fluid expansion tank	Optional	

Table of AD-Notes and Technical Notes

ALEXANDER SCHLEICHER

GMBH & CO

Segelflugzeugbau
D-36163 Poppenhausen

Type: **ASK 21Mi**

Data Sheet No.: **EASA.A.221**

Sheet: **3 of 4**

License: **DE.21G.0010**

TN-No	AD-No. Issue Date	TN Issue Date	Version & Serial no.s affected	Subject	Compliance	Inspection Ref.
14		22.05.18 EASA-app.: 12.10.17	all ASK 21 Mi	Improvement of the performance map of the new IAE50R-AA ECU with serial numbers "AE00XXX" which were installed as standard from 2014 onwards	During the next engine maintenance or next annual C of A inspection	
15 Issue II		07.08.23 EASA-app.: 31.07.23	all ASK 21 Mi	Cracks in the bonding of the wing root rib	Action 1 "Inspection for Cracks" until 31.12.2019 at the latest, afterwards annual Actions 2 and 3 if necessary	
16 Issue II		15.10.20 EASA-app.: 07.09.20	all ASK 21 Mi	Specification of service life limitations for the brake hoses of the hydraulic wheel brake	Optional	
17		04.11.20 EASA-app.: 18.12.20	all ASK 21 Mi	Clevis pins on the connection point of control cable and rudder	Optional, in case of wear of the brass bushings	
18		16.11.20 EASA-app.: 18.12.20	all ASK 21 Mi	Towing cable release handle in the front cockpit moved upwards	Optional	
19		05.05.22 EASA-app.: 16.06.21	all ASK 21 Mi equipped with TN 2	Hand lever for rudder control	Optional	
20 Issue III		11.12.25 EASA-app.: 27.01.26	all ASK 21 Mi	Further product improvements	Optional	

Table of AD-Notes and Technical Notes

ALEXANDER SCHLEICHER

GMBH & CO

Segelflugzeugbau

D-36163 Poppenhausen

Type: **ASK 21Mi**

Data Sheet No.: **EASA.A.221**

Sheet: **4 of 4**

License: **DE.21G.0010**

TN-No	AD-No. Issue Date	TN Issue Date	Version & Serial no.s affected	Subject	Compliance	Inspection Ref.
21		21.09.22 FAA-app.: 12.06.23	ASK 21 Mi Type-Certificate FAA G47EU	Registration as FAA Standard C of A	In case of registration as FAA Standard C of A	
22		07.08.23 EASA-app.: 31.07.23	all ASK 21 Mi with TN 3 and/or TN 20	Revision of the maintenance manual	31.12.2023	
23		07.08.23 EASA-app.: 31.07.23	all ASK 21 Mi	Alternative rotor cooling air intake filter	Optional	
24		09.10.23 EASA-app.: 30.10.23	all ASK 21 Mi	Fuel main filter	Optional	