

Doc.-No. 336-99-0001-00 Issue: 04 Date: 22.07.2026 Page: 1 of 14	List of applicable publications AS 33 Es	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
---	---	---

Section A: Manuals

Doc.- Number	Name	Issue	Date	Applicability												Remarks
				Model	Serial- Numbers	EASA	UK	Australia	New Zealand	Canada						
Aircraft flight manuals																
---	Flughandbuch für das nicht eigenstartfähige Segelflugzeug AS 33 Es (German)	---	25.08.2020	AS 33 Es	33001 – 33009 & 33015	X	-	-	-	-						Only applicable unless TN 01 is performed
---	Flight manual for the self-sustaining powered sailplane AS 33 Es (English)	---	25.08.2020	AS 33 Es	33001 – 33009 & 33015	X	X	-	-	-						
---	Flughandbuch für das nicht eigenstartfähige Segelflugzeug AS 33 Es (German)	---	01.11.2020	AS 33 Es	all	X	-	-	-	-						
---	Flight manual for the self-sustaining powered sailplane AS 33 Es (English)	---	01.11.2020	AS 33 Es	all	X	X	X	X	X						
Supplements to aircraft flight manual																
---	Ergänzung B – Batterie in der Rumpfröhre (German)	---	28.04.2021	AS 33 Es	all	X	-	-	-	-						For aircraft with optional battery in the fuselage tail cone
	Supplement B – Battery in fuselage tail cone (English)					X	X	X	X	X						

Doc.-No. 336-99-0001-00 Issue: 04 Date: 22.07.2026 Page: 2 of 14	List of applicable publications AS 33 Es	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
---	---	---

Doc.- Number	Name	Issue	Date	Applicability													Remarks
				Model	Serial- Numbers	EASA	UK	Australia	New Zealand	Canada							
Aircraft maintenance manuals																	
---	Wartungshandbuch für das nicht eigenstartfähige Segelflugzeug AS 33 Es (German)	---	25.08.2020	AS 33 Es	33001 – 33009 & 33015	X	-	-	-	-							Only applicable unless TN 01 is performed
---	Maintenance manual for the self-sustaining powered sail-plane AS 33 Es (English)	---	25.08.2020	AS 33 Es	33001 – 33009 & 33015	X	X	-	-	-							
---	Wartungshandbuch für das nicht eigenstartfähige Segelflugzeug AS 33 Es (German)	---	01.11.2020	AS 33 Es	all	X	-	-	-	-							
---	Maintenance manual for the self-sustaining powered sail-plane AS 33 Es (English)	---	01.11.2020	AS 33 Es	all	X	X	X	X	X							
Supplement to aircraft maintenance manuals																	
---	Ergänzung A – VHF-Antenne im Seitenruder (German)	---	19.03.2021	AS 33 Es	all	X	-	-	-	-							For aircraft with optional radio antenna in the rudder
	Supplement A – VHF antenna in the rudder (English)					X	X	X	X	X							
---	Ergänzung B – Batterie in der Rumpfröhre (German)	---	28.04.2021	AS 33 Es	all	X	-	-	-	-							For aircraft with optional battery in the fuselage tail cone
	Supplement B – Battery in fuselage tail cone (English)					X	X	X	X	X							

Doc.-No. 336-99-0001-00 Issue: 04 Date: 22.07.2026 Page: 3 of 14	List of applicable publications AS 33 Es	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
---	---	---

Doc.- Number	Name	Issue	Date	Applicability													Remarks
				Model	Serial- Numbers	EASA	UK	Australia	New Zealand	Canada							
---	Ergänzung SP – Umrüstung Schwerpunktkupplung (German)	---	21.10.2022	AS 33 Es	all	X	-	-	-	-							For aircraft with TN 7 only
	X					X	X	X	X								
Aircraft repair manuals																	
---	Reparaturhandbuch (German)	---	13.04.1999	AS 33 Es	all	X	-	-	-	-							
---	Repair manual (English)	---	13.04.1999	AS 33 Es	all	X	X	X	X	X							
Supplement to aircraft repair manuals																	
---	Technische Mitteilung Nr. 01-99 für alle Flugzeugmuster in Fa- serverbundbauweise (German)	---	12.03.1999	AS 33 Es	all	X	-	-	-	-							
---	Technical note No. 01-99 for all aircraft types of glass fiber & Fi- ber Composite Construction (English)					X	X	X	X	X							
---	Technische Mitteilung Nr. 03-99 für alle Flugzeugmuster der ASH, ASK & ASW-Baureihen (German)	---	26.03.1999	AS 33 Es	all	X	-	-	-	-							
---	Technical note No. 03-99 for all aircraft of the production series ASH, ASK & ASW (English)					X	X	X	X	X							

Doc.-No. 336-99-0001-00 Issue: 04 Date: 22.07.2026 Page: 4 of 14	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	AS 33 Es	

Doc.- Number	Name	Issue	Date	Model	Serial- Numbers	Applicability										Remarks
						EASA	UK	Australia	New Zealand	Canada						
---	Technische Mitteilung Nr. 02-99 für alle Flugzeug- und Propeller-muster (German)	04	21.02.2023	AS 33 Es	all	X	-	-	-	-						
---	Technical Note No. 02-99 for all aircraft and propeller types (English)					X	X	X	X	X						

Doc.-No. 336-99-0001-00 Issue: 04 Date: 22.07.2026 Page: 5 of 14	List of applicable publications AS 33 Es	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
---	---	---

Section B: Maintenance instructions

Doc.- Number	Name	Issue	Date	Applicability													Remarks
				Model	Serial- Numbers	EASA	UK	Australia	New Zealand	Canada							
Type-specific maintenance instructions																	
---	ASW 24 Wartungsanweisung C „Reparaturanleitung des Kastens für Fahrwerk“ (German)	01	26.04.1990	AS 33 Es	all	X	-	-	-	-							
	ASW 24 Maintenance instruction C „Repair of the landing gear box“ (English)					X	X	X	X	X							
---	ASW 27-18 Wartungsanweisung D “Reparatur der Rumpfröhre durch Schäften“ (German)	01	19.09.2007	AS 33 Es	all	X	-	-	-	-							
	ASW 27-18 Maintenance instruction D „Repair of the tailcone by scarfing“ (English)					X	X	X	X	X							
---	ASW 27-18 E Wartungsanweisung E „Austausch der Gasdruckfeder oder der Hubspindel im Motorraum“ (German)	01	01.09.2009	AS 33 Es	all	X	-	-	-	-							
	ASW 27-18 E Maintenance instruction E „Replacement of the gas spring or spindle in the engine bay“ (English)					X	X	X	X	X							

Doc.-No. 336-99-0001-00 Issue: 04 Date: 22.07.2026 Page: 6 of 14	List of applicable publications AS 33 Es	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
---	---	---

Doc.- Number	Name	Issue	Date	Applicability												Remarks
				Model	Serial- Numbers	EASA	UK	Australia	New Zealand	Canada						
---	ASW 27-18 E Wartungsanweisung F „Durchführung von Motorstandläufen am Boden“ (German)	01	03.09.2015	AS 33 Es	all	X	-	-	-	-						
	ASW 27-18 E Maintenance instruction F „Performing an engine test run on the ground“ (English)					X	X	X	X	X						
---	ASW 27-18 E Wartungsanweisung G „Aus- und Einbau des Starters; Einstellen der Nullposition“ (German)	01	03.09.2015	AS 33 Es	all	X	-	-	-	-						
	ASW 27-18 E Maintenance instruction G „Dis- and re-assembling of the starter motor; adjusting the reference position“ (English)					X	X	X	X	X						
---	AS 33 Wartungsanweisung A „Elastische Abdeckbänder und Turbulatoren“ (German)	02	16.09.2021	AS 33 Es	all	X	-	-	-	-						
	AS 33 Maintenance instruction A “Elastic fairing tapes and turbulators” (English)					X	X	X	X	X						

Doc.-No. 336-99-0001-00 Issue: 04 Date: 22.07.2026 Page: 7 of 14	List of applicable publications AS 33 Es	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
---	---	---

Doc.- Number	Name	Issue	Date	Applicability													Remarks
				Model	Serial- Numbers	EASA	UK	Australia	New Zealand	Canada							
---	AS 33 Wartungsanweisung B „Reparatur Rumpflebenahmt im Cockpitbereich“ (German)	01	25.08.2020	AS 33 Es	all	X	-	-	-	-							
	AS 33 Maintenance instruction B “Repair of overlap joint in the cockpit area” (English)					X	X	X	X	X							
General maintenance instructions																	
---	Wartungsanweisung „Brandschutzfarbe im Motor- raum“ (German)	03	07.07.2022	AS 33 Es	all	X	-	-	-	-							
	Maintenance instruction “Fire protection paint in the en- gine compartment” (English)					X	X	X	X	X							
---	Wartungsanweisung „Alle GFK- Muster“ (German)	02	02.11.2020	AS 33 Es	all	X	-	-	-	-							
	Maintenance instruction „All FRP glider models“ (English)					X	X	X	X	X							
---	Wartungsanweisung über den Einbau von Ausrüstung (Ger- man)	02	25.04.2016	AS 33 Es	all	X	-	-	-	-							
	Maintenance instruction installa- tion of equipment (English)					X	X	X	X	X							
---	Wartungsanweisung „LACK- RISSE“ (German)	---	26.06.1989	AS 33 Es	all	X	-	-	-	-							

Doc.-No. 336-99-0001-00 Issue: 04 Date: 22.07.2026 Page: 8 of 14	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	AS 33 Es	

Doc.- Number	Name	Issue	Date	Applicability												Remarks
				Model	Serial- Numbers	EASA	UK	Australia	New Zealand	Canada						
	Maintenance instruction "PAINT CRACKS" (English)					X	X	X	X	X						

Doc.-No. 336-99-0001-00 Issue: 04 Date: 22.07.2026 Page: 9 of 14	List of applicable publications AS 33 Es	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
---	---	---

Section C: Service bulletins

Doc.- Number	Name	Issue	Date	Applicability												categorisation ¹	manual rev. ²	urgency	Remarks	
				Model	Serial No.	EASA	UK	Australia	New Zealand	Canada										
Type-specific service bulletins																				
AS 33 Es TN No. 1	Erweiterung Flugbereich (German)	---	09.03.2021	AS 33 Es	33001 - 33009 & 33015	X	-	-	-	-							M	AFM AMM	31.12.2021	
	Expansion of flight-enve- lope (English)					X	X	X	X	X										
AS 33 Es TN No. 2	Einbau Tankerweiterung Kraftstoffsystem (German)	---	09.03.2021	AS 33 Es	all	X	-	-	-	-							O	---	none	
	Installation of a fuel tank extension (English)					X	X	X	X	X										
AS 33 Es TN No. 3	Batteriehalterung Ausfüh- rung 2 im Gepäckraum (German)	---	28.04.2021	AS 33 Es	all	X	-	-	-	-							O	AFM	none	
	Battery holder version 2 in the baggage compartment (English)					X	X	X	X	X										
AS 33 Es TN No. 4	15m Außenflügel (German)	02	03.01.2022	AS 33 Es	all	X	-	-	-	-							O	AFM AMM	none	
	15m outer wings (English)					X	X	X	X	X										
AS 33 Es TN No. 5	Flügelrädchen (German)	---	08.03.2023	AS 33 Es	all	X	-	-	-	-							O	---	non	
	Wing tip wheels (English)					X	X	X	X	X										

¹ M = Mandatory, R = Recommended, O = Optional

² AFM = Revision of Flight Manual, AMM = Revision of Maintenance Manual, -Sup = New supplement to AFM / AMM

Doc.-No. 336-99-0001-00 Issue: 04 Date: 22.07.2026 Page: 10 of 14	List of applicable publications AS 33 Es	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
--	---	---

Doc.- Number	Name	Issue	Date	Applicability													categorisation ¹	manual rev. ²	urgency	Remarks
				Model	Serial No.	EASA	UK	Australia	New Zealand	Canada										
AS 33 Es TN No. 6	Gelenkköpfe Quersteuerung (German)	02	08.03.2023	AS 33 Es	33003 - 33051	X	-	-	-	-							R	---	31.03.2023	
	Push rod end bearings aileron control (English)					X	X	X	X	X										
AS 33 Es TN No. 7	Schwerpunktkupplung (German)	---	22.03.2023	AS 33 Es	all	X	-	-	-	-							O	AMM -Sup	none	
	C.G.-hook (English)					X	X	X	X	X										
AS 33 Es TN No. 8	Ergänzung Wartungshandbuch (German)	---	07.08.2023	AS 33 Es	all	X	-	-	-	-							M	AMM	31.12.2023	
	Revision of the maintenance manual (English)					X	X	X	X	X										
336-99-0002-00/01	AS 33 Es - TM 9 – Brems-schlauchverlegung (German)	00	16.10.2024	AS 33 Es	all	X	-	-	-	-							O	---	none	
	AS 33 Es - TN 9 – Brake hose routing (English)					X	X	X	X	X										
General service bulletins																				
TM Nr. 01-2005	Verwendung von Hart-schaumstoff gemäß Werkstoff-Leistungsblatt 5.1460.2 (German)	---	24.02.2005	AS 33 Es	all	X	X	X	X	X							O	---	none	
TN No. 02-2005	Anerkannte Reparaturverfahren nach EU-VO	---	24.05.2005	AS 33 Es	all	X	-	-	-	-							O	---	none	

Doc.-No. 336-99-0001-00 Issue: 04 Date: 22.07.2026 Page: 11 of 14	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	AS 33 Es	

Doc.- Number	Name	Issue	Date	Applicability												categorisation ¹	manual rev. ²	urgency	Remarks
				Model	Serial No.	EASA	UK	Australia	New Zealand	Canada									
	1702/2003, Teil 21, Abschnitt M (German)																		
	Approved repair procedures according to EU-VO 1702/2003, Part 21, section M (English)					X	X	X	X	X									
TN No. 02-2008	Anweisung für den Einbau von Ausrüstung (German)	04	21.02.2023	AS 33 Es	all	X	-	-	-	-						O	---	none	
	Instruction for the installation of equipment (English)					X	X	X	X	X									
TN No. 02-2013	Verwendung von Pyrofil TR30S- 3K (German)	03	21.02.2023	AS 33 Es	all	X	-	-	-	-						O	---	none	
	Usage of Pyrofil TR30S-3K (English)					X	X	X	X	X									
TN No. 01-2020	Ersatz für Polyestervlies PKM 80, Molton oder Flanell 406 (German)	03	21.02.2023	AS 33 Es	all	X	-	-	-	-						O	---	none	
	Replacement for polyester fleece PKM 80, Molton or Flanell 406 (English)					X	X	X	X	X									

Doc.-No. 336-99-0001-00 Issue: 04 Date: 22.07.2026 Page: 12 of 14	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	AS 33 Es	

Doc.- Number	Name	Issue	Date	Applicability												categorisation ¹	manual rev. ²	urgency	Remarks
				Model	Serial No.	EASA	UK	Australia	New Zealand	Canada									
TN No. 02-2020	Einbau AIR Control Display 57 (ACD-57) als primärer Höhenmesser (German)	02	21.02.2023	AS 33 Es	all	X	-	-	-	-						O	--	none	
	Installation of AIR Control Display 57 (ACD-57) as primary altimeter (English)					X	X	X	X	X									

Doc.-No. 336-99-0001-00 Issue: 04 Date: 22.07.2026 Page: 13 of 14	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	AS 33 Es	

Section D: Service Information

Doc.- Number	Name	Issue	Date	Applicability												categorisation ³	manual rev. ⁴	urgency	Remarks
				Model	Serial No.	EASA	UK	Australia	New Zealand	Canada									
99.090.9028	Arbeitsanweisung "Einbau Flarmantenne hinter FW-Klappe" (German)	D	05.01.2023	AS 33 Es	all	X	X	X	X	X						O	--	none	
336-99-0005-00	Flap lever locking pin	00	22.07.2026	AS 33 Es	all	X	X	X	X	X						M	---	none	

³ M = Mandatory, R = Recommended, O = Optional

⁴ AFM = Revision of Flight Manual, AMM = Revision of Maintenance Manual, -Sup = New supplement to AFM / AMM

Doc.-No. 336-99-0001-00 Issue: 04 Date: 22.07.2026 Page: 14 of 14	List of applicable publications AS 33 Es	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
--	---	---

Section E: Notes

1. For countries not listed in the tables the owner/operator of the aircraft has to check the applicability of the respective Manual/Service-Bulletin/Service-Info based on the national legal regulations.
2. Mandatory and recommended Service-Bulletins or Service-Information has to be followed by the owner/operator of the aircraft. Non-compliance leads to exclusion of any liability.
3. The applicability of Revisions or Supplements to approved manuals (Flight / Maintenance / Repair) depends on the configuration of the aircraft and has to be checked for each individual serial number.

Section F: Change Record

Issue	Date	Changes
00	29.08.2023	Initial issue
01	29.08.2023	Hyperlinks added
02	20.06.2024	Canada added
03	16.10.2024	Service bulletin 336-99-0002-00/01 added
04	22.07.2026	Service information 336-99-0005-00 added