

Accomplishment: Improvement

Subject: Jettisoning devise for canopy.

Effectivity: Glider ASK 13; L-267 (G 15 EZ)
from S.Nb. 13285
incl. 13275, 13279; 13282
All other Gliders optional.

Instructions: After drawing L-267.11-S 2 the modification has to be made. The work will be done by the manufacturer.

Modification of the Flight Handbook:
On page 8:

Emergency Jettisoning of Canopy:

The sentence "To bail out, the canopy has to be opened at the release knob at the left side and pushed forward out of the hinge" has to be canceled.

New sentence: "To bail out the canopy has to be opened by pulling both release knobs on left and right side".

Supplementary drawings:

L - 267.11-S 2

6416 Poppenhausen, 17.12.1970

i.A. Prindl Fritz

ALEXANDER SCHLEICHER
Segelflugzeugbau