

Summary of Airworthiness Directives (AD) and Technical Notes (TN)

ALEXANDER SCHLEICHER

GMBH & CO

Segelflugzeugbau
D-36163 Poppenhausen

Type: **ASK 23**

Data Sheet No.: **353**

Sheet: **1 of 2**

License: **DE.21G.0010**

TN-No.	AD-No. Date of Issue	TN Date of Issue	Affected Production Series and Serial No.'s	Subject	Compliance	Inspector's stamp
1		10.05.85 LBA-appr.:10.06.85	all ASK 23 for registration in the Netherlands	Some structural modification are necessary for the Netherlands (Issue only in german language)	only for Export to Netherland	
1a		20.06.86 LBA-appr.:03.07.86	all ASK 23 and ASK 23 B for registration in the Netherlands	Some structural modification are necessary for the Netherlands (Issue only in german language)	only for Export to Netherland	
2	85-203 09.10.85	13.09.85 LBA-appr.:11.07.90	all ASK 23 up to S/N 23033, as of S/N 23034 serial standard	Installation of an additional bulkhead in the area of the nose wheel	action to be accomplished until the next annual C. of A. inspection, but before or on 31.03.1986, at the latest	
3		07.02.86 LBA-appr.:19.03.86	all ASK 23 up to S/N 23051, as of S/N 23052 serial standard	Modification to the model ASK 23 B	none; this is an optional modification	
4		29.09.86 LBA-appr.:06.10.86	all ASK 23 and ASK 23 B as of 23001 until 23076 except for 23068, as of S/N 23077 serial standard	Additional seatpan rest	optional mod only; we recommend this action to be accomplished by the next annual C. of A. inspection	
5		06.09.88 LBA-appr.:12.09.88	all ASK 23 and ASK 23 B	A. Improvement of the wheel brake B. Modification to the control stick	none; optional mod only	
6		10.05.90 LBA-appr.:25.06.90	all ASK 23 and ASK 23 B	ASK 23: Amendment of the Flight and Maintenance Manual ASK 23 B: Amendment of the Maintenance Manual	action to be accomplished until the next annual C. of A. inspection, but before or on 31.12.1990, at the latest	
7		17.01.90 LBA-appr.:01.03.90	all ASK 23 and ASK 23 B	New production series tow release couplings for aerotow and winch launch	none, applicable to new built gliders and in case of replacement of tow release couplings	

Summary of Airworthiness Directives (AD) and Technical Notes (TN)

ALEXANDER SCHLEICHER

GMBH & CO

Segelflugzeugbau
D-36163 Poppenhausen

Type: **ASK 23**

Data Sheet No.: **353**

Sheet: **2 of 2**

License: **DE.21G.0010**

TN-No.	AD-No. Date of Issue	TN Date of Issue	Affected Production Series and Serial No.'s	Subject	Compliance	Inspector's stamp
--------	-------------------------	---------------------	--	---------	------------	----------------------

8	90-350 18.12.90	26.11.90 LBA-appr.:04.12.90	all ASK 23 and ASK 23 B as of 23001 until 23121, as of S/N 23122 serial standard	Checking the parallel rocker (at the elevator actuator rod) in the fin. Exchange of this part and amendment to the Flight Manual.	Checking an –in case of damages found- exchanging the part prior to the next take-off. Otherwise the exchange has to be done until the next annual C. of A. inspection, but before or on 31.04.1991, at the latest.	
--	1993-001/3 09.04.98 supersedes 93-001/2 dated 20.04.94 and 93-001 dated 03.03.93	without	all ASK 23 and ASK 23 B	Locking of L'Hotellier connectors	action to be accomplished until the next annual C. of A. inspection, but before or on 30.04.1994, at the latest respectively 15.05.1998	
9		04.08.93 LBA-appr.:06.09.93	all ASK 23 and ASK 23 B	Wedekind safety sleeves Locking of L'Hotellier connectors	optional mod only	
10	93-196 27.09.93	14.09.93 LBA-appr.:17.09.93	all ASK 23 and ASK 23 B	Inspection of the main bulkhead II (landing gear bulkhead) for damages	action to be accomplished until the next annual C. of A. inspection, but before or on 31.03.1994, at the latest	
11		09.10.96 LBA-appr.:15.10.96	all ASK 23 and ASK 23 B	Product improvement – new trim spring mod	optional mod only	
12	97-244 28.08.97	16.06.97 LBA-appr.:22.07.97	all ASK 23 and ASK 23 B	A) Amendment of Maintenance Manual B) Inspection program to increase the service life	A) action to be accomplished until the next annual C. of A. inspection, but before or on 31.12.1997, at the latest B) prior to reaching a total service life of 3000 flight hours respectively	
13		28.06.99 LBA-appr.: 14.03.00	ASK 23 and ASK 23 B	Nose bolt with O-Ring for horizontal tail (provisional only in german issue)	optional standard on new production gliders	
14		05.02.08 EASA-gen.: 11.01.08	all ASK 23 and ASK 23 B all S/N	Installation of a transponder antenna inside the fuselage behind the landing gear	optional	