Page 1 of 1			ASH 26 E echnical Note No. 23	Alexander Schleicher GmbH & Co. Segelflugzeugbau D - 36163 Poppenhausen	
Subject:	Specific	ation update of th	e flexible fuel tanks		
Applicability:	ASH 26	ASH 26 E; Type-Certificate LBA 883; all serial numbers			
Classification:	Minor Change				
Urgency:	In case of replacement or new installation of a flexible fuel tank				
Reason:	It is necessary to update the specification of the flexible fuel tanks due to introducing a new manufacturer. The new flexible fuel tanks are made by the same processing, the materia is slightly different.				
Action:	The flexible fuel tanks are specified by their individual drawings:				
			made by Heimann (existing)	made by Streifeneder (new)	
	Drawin	ıg	99.010.3457	99.010.3472	
	Summarization of the installation and inspection instructions for flexible fuel tanks to "Wor ing Instruction No. 32 Installation and Inspection Instruction for Flexible Fuel Tanks, Issue				
	Exchange or modification of the following manual pages: Maintenance Manual: 4.6				
		This page has to be changed as follows:			
	The t		11. (1 1 . 11. 11. 11. 11. 11. 11. 11. 11. 11.		
	in the	"The flexible fuel tanks are subject to a service life limitation. The service life is specifie in the currently valid edition of the "Installation, Test & Inspection Instructions for flexib fuel tanks HFK T-LF."			
		has to be changed to			
	"The flexible fuel tanks are subject to a service life limitation. The service life is 16 year from date of manufacture considering the periodic inspections specified in the current valid issue of the "Installation and Inspection Instruction for Flexible Fuel Tanks" by A exander Schleicher."				
			ate in the field "Revision" in the	footer.	
Material and Drawings:	See Act	tion			
Mass and Balance:	The change in mass and C. of G. position is negligible.				
Notes:	cher or b	The structural measures must only be accomplished by the manufacturer Alexander Schle cher or by a maintenance organisation according to European Union Commission Regula tion (EC) 1321/2014 Part M / Section A / Subpart F.			
	All actions are to be inspected by certifying staff according to European Union Commission Regulation (EC) 1321/2014 Part M / Part 66 in the scope of a modification and have to be certified in the sailplane inspection documents and in the sailplane logbook. The changes the manual is considered being eligible for release by the Pilot-owner pursuant M.A.801(b)3 and must be entered on the page "Record of Revisions" and in the "List effective pages".				
		In countries outside the scope of EC 1321/2014 the corresponding national rules shall ap ply.			
Poppenhausen, 1	5.09.2017				
, , , , , , , , , , , , , , , , , , ,				ler Schleicher nbH & Co.	
				P. A.	
This Technical No 10063159.	te bases or	n a change, which	was approved by EASA under	the minor change approval EAS	