

Subject: Wing tip extension 26.9 m
Applicability: Type: ASW 22, Type-Certificate EASA.A.217; Models: ASW 22 BLE and ASW 22 BLE 50R; **serial numbers 22050, 22082, 22083, 22084**
Classification: Major Change
Urgency: optional
Reason: Product improvement
Action: The accomplishment of TN 8 a/b is required for the application of this change.
New wing tip extension according drawing 226.51.9022
Exchange of the following manual pages:
Flight manual page 9.2
Supplement of the following manual pages:
Flight manual appendix A


Material and Drawings: See Action

Mass and Balance: The new mass and C. of G. position have to be determined.

Notes: The structural measures must only be accomplished by the manufacturer Alexander Schleicher.
All actions have to be inspected as non-complex maintenance by certifying staff according to M.A.801 (EC 1321/2014) and have to be certified in the sailplane inspection documents and in the sailplane logbook. The change to the manual is considered being eligible for release by the pilot-owner pursuant to M.A.801(b)3 and must be entered on the page „Record of Revisions“ and in the „List of effective pages“.
In countries outside the scope of EC 1321/2014 the corresponding national rules shall apply.

Poppenhausen, 25.05.2020

Alexander Schleicher
GmbH & Co.

i.A. 
(P. Anklam)

This Technical Note bases on a change, which was approved by EASA under the major change approval EASA 10073419.