

Oxygen Equipment

For oxygen systems fitted, the relevant section of the appertaining Manufacturer's Inspection Release Certificate states the overhaul time limit. Over and beyond this, the oxygen bottles must be re-inspected by a technical inspection institute every five years in accordance with pressure vessel regulations.

Special Servicing Procedures

Brake line hoses of the "old type" must be replaced at regular intervals of 6 years. Should this hose be in good condition, it need not be replaced, if its condition is checked at least every 100 flying hours.

Brake line hoses of the "new type" have no service life time limitation.

The identification of the brake line hose type is possible by accomplishing technical note TN 42.