Page 1 of 1		AS 33 Es Technical Note No. 3	Alexander Schleicher GmbH & Co. Segelflugzeugbau D - 36163 Poppenhauser
Subject:	Battery holder version 2	in the baggage compartment	
Applicability:	AS 33 Es; Type-Certificate EASA.A.656; all serial numbers		
Classification:	Minor Change		
Urgency:	optional		
Reason:	Product improvement		
	stalled and removed on version 2 allows to rem	v holder in the upper baggage comp ly if the wings were removed. The r ove the battery if the aircraft is riggen has to be removed for de-rigging the	new (alternative) battery holde
Action:	Installation of the battery holder version 2 (AS P/N 330.11.1014) in the upper baggag compartment on right-hand side in the existing cut-out at the floor. The fastening by the tw screws at the baggage compartment floor remains unchanged.		
	The following pages at	the flight manual have to be exchan	ged.
	Flight Manual:	4.6, 7.16	
	Maintenance Manual:	none	
	The new manual pages are marked with the technical note number TN 03 from April 202 as revision.		
Material and Drawings:	See Action		
Mass and Balance:	The change in mass and C. of G. position can be neglected.		
Notes:	The production of parts have to be accomplished by the manufacturer Alexander Schle cher GmbH & Co or a company authorised by the manufacturer.		
	The installation of the battery holder has to be considered as a pilot-owner maintenance task regarding aviation law. The respective regulations must be applied.		
Poppenhausen, 28	3.04.2021		
			r Schleicher H & Co.
		i.A.	pus -
			/lörsel)