

Subject: Amendment of manuals

Applicability: **ASK 21 B**; Type Certificate EASA.A.221; all serial numbers

Classification: Minor Change

Urgency: 31.12.2022

Reason: Improvement of system description in the manuals
More detailed descriptions and instructions for the usage and maintenance of trim ballast and spin ballast will be available for the operators of ASK 21 B sailplanes.

Action: Exchange of the following manual pages:

- ASK 21 B flight manual German: 4.17, 7.14, 7.15, 7.16, 7.17
- ASK 21 B flight manual English: 4.17, 7.14, 7.15, 7.16, 7.17
- ASK 21 B maintenance manual German: 7.5
- ASK 21 B maintenance manual English: 7.5

The replacement pages are marked with the belonging TN No. and the date of change 05.05.22.

The exchange of the page at the manual must be documented in section 0.1 "Record of Revisions".

Material and Drawings: See action

Mass and Balance: No change in mass and centre of gravity position.

Notes: The exchange of manual pages has to be considered as a pilot/owner maintenance task regarding aviation law. The respective national regulations must be applied.

Poppenhausen, 20.06.2022

Alexander Schleicher
GmbH & Co.

i. A. 
(T. Mörsel)

This Technical Note bases on a change which was approved by EASA under the minor change approval EASA 10079522.