

Doc.-Nr. 280-99-0001-00 Issue: 00 Page: 1 of 1	Technical Note	Alexander Schleicher GmbH & Co. Segelflugzeugbau D-36163 Poppenhausen ADOA AP138
	ASW 28 - TN 14 Correction maintenance manual	

Issue date: 02.12.2024

Subject: Revision of the maintenance manual

Applicability: ASW 28, all serial numbers

Urgency: At the next scheduled maintenance action from date of revision.

Material: See action

Drawings: See action

Mass and Balance: No change in mass and C. of G. position.

Notes: The actions have to be considered as a pilot-owner maintenance task regarding aviation law. The respective regulations must be applied.

Approval: This Technical Note bases on a change, which was approved by EASA under the minor change approval EASA 10088174.

Actions

The following pages of the manuals have to be exchanged.

Maintenance manual page 5.2

The new manual pages are marked with the technical note number “TN 14 02.12.24” as revision.

The exchange of the pages has to be noted in the record of revision of the manual. The list of effective pages must be updated, too.